
PLANT II

WASTE DISPOSAL STAGING AREAS: DRUMS AND TANKAGE



- (1) DRUMMED WASTE STAGING AREA.
- (2) FREE AND SOLUBLE WASTE OIL HOLD AREA.
- (3) 5,000 GAL. TANK WASTE ACID.

- (4) 4,000 GAL. TANK CONCENTRATED CHROME BEARING RINSE (FROM EVAPORATOR).
- (5) 800 GAL. SUMP WASTE SOLVENT.
- (6) CYANIDE WASTE HOLD AREA.

GENERAL FACILITY INFORMATION, HAZARDOUS WASTE MANAGEMENT OPERATIONS BOEING AEROSPACE COMPANY, PLANT II SEATTLE, WASHINGTON, SEPTEMBER 1987

